

You may have noticed the repair work taking place on the ornamental lintel at the entrance of McKenzie City Hall. Due to problems with maintenance through the years, the Styrofoam and wood structure has encountered problems with moisture seeping in through the porous Dryvit coating on the outside. This has resulted in the wood decaying and a weakening of the structure. The lintel was removed for safety reasons; however, the brick columns will remain. The letters for the municipal center will be replaced on the front of the building above the entrance. Plans are being made to clean and repaint the Dryvit on the building in order to insure the longevity and integrity of the existing Dryvit.